

**UST CLOSURE  
INSPECTION CHECKLIST**

Inspector's Name Sharon K. Cilas Date March 6, 2001

**I. SITE INFORMATION**

Facility/Site Name: V+E Components, Inc.  
 City/Town: 2130 Brewster Road, High Point County: Huilton  
 Owner: Mr. Everett West Phone: (336) 434-4109  
 Operator: \_\_\_\_\_ Phone: \_\_\_\_\_  
 Contractor: \_\_\_\_\_ Phone: \_\_\_\_\_  
 Laboratory: \_\_\_\_\_ Phone: \_\_\_\_\_  
 Directions: \_\_\_\_\_

Date of scheduled UST Removal (from GW/UST-3): 3-6-01

**II. UST STATUS**

Tank #:	1	2	3	4	5	6	7	8
Size:	<u>6,000</u>							
Product:	<u>#2 fuel oil</u>							

Remark Y (YES), N (NO), NA (NOT APPLICABLE), and U (UNKNOWN) for each of the following:

**III. CLOSURE PROCEDURES**

☐ Tanks, tools, equipment bonded or grounded?  
☐ OSHA/Safety violations observed: \_\_\_\_\_  
☒ Product in piping drained into tank?  
☒ Tanks properly purged? Method: lined by O.K. Enterprises  
☒ Tanks emptied and cleaned properly?  
☒ Accessible openings capped or plugged except 1/8" vent?  
☒ UST(s) closed in place and filled with solid inert material?  
 Final destination of tank(s): O.K. Enterprises  
 Final destination of product, contaminated soil, contaminated water, etc. \_\_\_\_\_

**IV. SITE DESCRIPTION**

☒ Soil stained and/or petroleum odor?  
☒ Contaminated soil excavated? Quantity? (estimate): \_\_\_\_\_  
☒ Soil samples taken of excavated soil left on site?  
 Excavated soil on plastic or trucked away? (Circle one)  
 Tank(s) condition: \_\_\_\_\_  
 Product line condition?: \_\_\_\_\_

**V. SAMPLING LOCATION**

☒ USTs < 20': one at each end?  
☒ USTs > 20': one at each end & middle?  
☒ Samples every 20' of piping?  
☒ Samples under each tank island?  
☒ Water samples? (in lieu of soil samples)  
 Samples: floor side, stockpiled soil?: \_\_\_\_\_

**VI SAMPLE COLLECTION QUALITY CONTROL**

Collection method: (Shovel, auger, back hoe): *line sample taken with hand auger*  
 How Preserved? (ice):  
 Tools decontaminated: (soap, Di-H<sub>2</sub>O, MECH, organic-free H<sub>2</sub>O).  
 Chain-of-Custody form (required):

**VII SUMMARY OF SITE CONDITIONS**

☒ Groundwater intersected?  
☒ Bedrock encountered?  
☒ Contaminated soil?  
☒ Free product in excavation?

**VIII SAMPLES COLLECTED BY DEM PERSONNEL**

☒ Samples collected?  
 Sample locations:

**XV COMMENTS:**

*190 LEL before pulling  
 Tank in fair cond, some pitting + corrosion, no holes noted.  
 Samples ~ 11' BLS for UST*

**DIAGRAM OF SITE INVESTIGATION AT UST CLOSURE**

Diagram should include physical structures such as roads, buildings, etc.; former location of USTs, pumps, product lines; soil sampling locations; and location of excavated soil.

*Brevard Road*

